

This machine had an optional front scrubbing attachment that almost never got installed. The main sweeping brushes are 42".




Fig. 2 – Replacement Brushes

05613

42"

Key	TENNANT Part No.	Machine Serial Number	Description	Qty.
1	22071N	(000000– )	Main Brush, 8 Row Nylon	1
1	22551	(000000– )	Main Brush, 8 Row Polypropylene	1
1	22643	(000000– )	Main Brush, 8 Row Polypropylene and Wire	1
1	22620	(000000– )	Main Brush, 8 Row Union Mix and Wire	1
1	<del>22551</del> <b>43898</b>	(000000– )	Main Brush, 5 Row Nylon	1
1	<del>22071N</del> <b>43430N</b>	(000000– )	Main Brush, 24 Row Nylon	1
1	<del>22620</del> <b>22619</b>	(000000– )	Main Brush, 24 Row Union Mix and Wire	1
1	<del>22072A</del>	<del>(000000– )</del>	<del>Main Brush, 24 Row Union Mix</del>	<del>1</del>
	43708P	(000000– )	Side Brush Assembly, Polypropylene	1
2	09600P	(000000– )	Side Brush, Polypropylene	1
3	47501	(000000– )	Hub, Brush Adaptor	1
	43708N	(000000– )	Side Brush Assembly, Nylon	1
	09600N	(000000– )	Side Brush, Nylon	1
	47501	(000000– )	Hub, Brush Adaptor	1
	<del>46857</del>	<del>(000000– )</del>	<del>Side Brush Assembly, Scrub, Polypropylene</del>	<del>1</del>
4	<del>43148</del>	<del>(000000– )</del>	<del>Side Brush, Scrub, Polypropylene</del>	<del>1</del>
5	<del>43554</del>	<del>(000000– )</del>	<del>U-Joint, Side Brush Drive</del>	<del>1</del>
	<del>46858</del>	<del>(000000– )</del>	<del>Side Brush Assembly, Scrub, Polypropylene</del>	<del>1</del>
	<del>43593</del>	<del>(000000– )</del>	<del>Side Brush, Scrub, Polypropylene</del>	<del>1</del>
	<del>43554</del>	<del>(000000– )</del>	<del>U-Joint, Side Brush Drive</del>	<del>1</del>
6	43592	(000000– )	Scrub Brush, 24 Row Polypropylene	1
6	<del>43424</del>	<del>(000000– )</del>	<del>Scrub Brush, 24 Row Polypropylene</del>	<del>1</del>
6	<del>43680</del>	<del>(000000– )</del>	<del>Scrub Brush, 24 Row Abrasive</del>	<del>1</del>
6	<del>22071N</del> <b>43262</b>	(000000– )	Scrub Brush, 8 Row Nylon	1

38"